




No.	Part	Material
1	Washer	EPDM
2	Insert	CW617N
3	Nut	HPb57-3
4	Ferrule	SS304
5	Hose	SS304 braiding/ PVC inner tube
6	Washer	EPDM

Working Temperature	Working Pressure	Burst Pressure
23-82°C	Max.125 psi	3.5 MPa

Item No.	Description
64418-WMH	Washing Machine F3/4"X F3/4 X 60"