




No.	Part	Material
1	Insert	C37100
2	Washer	santoprene
3	Nut	HPb57-3
4	Ferrule	SS304
5	Hose	SS304 braiding/ PVC inner tube
6	Male	C37100
7	Sleeve	H62
8	Nut	HPb57-3
9	Washer	EPDM

Working Temperature	Working Pressure	Burst Pressure
23-82°C	Max.125 psi	3.5 MPa

Item No.	Description
64406-FH	F3/8C x FM3/8C x 12"
64408-FH	F3/8C x FM3/8C x 20"